CamTrax64 Quick Start Guide

Set CamTrax64 to use the SolidWorks serial number

Enter the registration code provided by Camnetics, Inc.

Accept the license agreement

Add a cam blank by clicking on the **Add New Cylinder to Assembly** tool bar button

Change the **Blank Diameter** and **Height**

Add a path to the cam blank by clicking on the **Insert New Path** tool bar button
Change the **Follower Size Nominal** to 1-5/8 diameter
Change the **Path Depth** to 1.125

Add a segment to the cam path by clicking on the **Add Segment to Current Path** tool bar button
Change the end angles to 180 and 360 degrees respectively

Change the motion types to **Harmonic** for both segments

Open the Chart window by clicking on the **Open Chart Window** tool bar button

Open the **Create CAD Models and Assemblies** by clicking on the tool bar button or the **CAD>Create CAD Models and Assemblies** menu item

Keep the default settings and press the **Create in SolidWorks** button to create the CAD model

The completed CAD model in SolidWorks